

Amendments to the Specification:

Please add, beginning at page 11, between lines 2 and 3 of the Substitute Specification filed on June 29, 2005, the following new paragraph:

Figure 9 also shows an opening 41 (illustrated in dashed line) in the rotor blade tip. Water can drain through the opening 41.